

# ENERGY AND ENVIRONMENT CABINET

**Matthew G. Bevin**  
Governor

**Department for Natural Resources**  
Division of Mine Safety  
300 Sower Boulevard  
Frankfort, Kentucky 40601  
Phone (502) 573-0140  
Fax (502) 573-0152

**Charles G. Snaveley**  
Secretary

**John Small**  
Commissioner

## **EMERGENCY AWARENESS BULLETIN**

**(EAB – No. 1 – 2018)**

### **Kentucky DMS – Fatal Accident No.1**

A 29-year-old Foreman/Belt Man with 8 years of mining experience, 1 years at this occupation, was fatally injured in the Harlan Branch.

He was positioned between the structure as he and a co-worker were replacing a bad splice when the belt unexpectedly started. This resulted in him becoming entangled in the conveyor belt and splicing equipment as he was taken down the entry.

### **BELT SPLICING LOCATION**



### **RECOMMENDATIONS TO PREVENT A SIMILAR OCCURRENCE**

1. Never perform work on machinery until it has been locked and tagged out of service and blocked against motion.
2. Stop and start controls are not an adequate means to de-energize electrical circuits, instead, utilize proper disconnect devices that are locked and tagged by those performing the work.
3. All electrical work shall be performed by or under the direct supervision of a certified electrician.
4. Evaluate each work assignment to identify and remove potential risk.